
















Z-axis

X-axis

Y-axis



Z-axis spacer (x2)



Motor coupling (x3)

Motor bracket (x3)